





SGT Measurement Guideline



We Suggest you to.....

To get better results, we recommend you to measure in the following conditions:

1. With a stable light source and fixed measurement distance
2. Continuous spectrum (like the standard light source A)
3. Over 5,000 lux



Don't Suggest You to.....

In these kinds of light sources, the deviation of results might be huge, due to the low intensity of those “marked” wavelengths. The random noises will influence the results of those wavelengths sharply.

